
P√σ
Constant power AV.
Constant thrust AV.
Power required
ḣmax (constant thrust)
ḣmax (constant power)
Ve